

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

BLANDAIR
6651 Highway 175
Columbia
Howard County
Maryland

HABS No. MD-1149

James Rosenthal, Photographer, 2003-04

- MD-1149-1 North (front) elevation of main block
- MD-1149-2 North (front) elevation of main block, with scale stick
- MD-1149-3 North (front) elevation of service wing, with scale stick
- MD-1149-4 Detail of front entrance, with scale stick
- MD-1149-5 Detail of cellar and first floor windows, with scale stick
- MD-1149-6 View looking southwest
- MD-1149-7 View looking northwest
- MD-1149-8 South (rear) elevation, with scale stick
- MD-1149-9 South (rear) elevation of service wing, with scale stick
- MD-1149-10 Detail of rear service wing door, with scale stick
- MD-1149-11 Detail of rear entrance
- MD-1149-12 Detail of rear entrance, with scale stick
- MD-1149-13 Detail of second story rear window / jib door
- MD-1149-14 View looking northeast
- MD-1149-15 Detail of cornice at southwest corner, showing granite dentil block
- MD-1149-16 View of first floor Center Hall (Room 101), looking south

- MD-1149-17 Detail of ceiling medallion in Center Hall (Room 101)
- MD-1149-18 Detail of newel post
- MD-1149-19 Detail of newel post, with scale stick
- MD-1149-20 View of South Parlor (Room 103), looking northwest into North Parlor (Room 102)
- MD-1149-21 Detail of fireplace in South Parlor (Room 103), with scale stick
- MD-1149-22 Detail of fireplace in North Parlor (Room 102), with scale stick
- MD-1149-23 Detail of ceiling medallion in North Parlor (Room 102)
- MD-1149-24 Detail of fireplace in Dining Room (Room 105), with scale stick
- MD-1149-25 View of Kitchen (Room 109), looking northeast
- MD-1149-26 Detail of fireplace in Kitchen (Room 109), with scale stick
- MD-1149-27 Detail of stair at second floor, looking south
- MD-1149-28 View of second floor Center Hall (Room 201), looking north, with scale stick
- MD-1149-29 Detail of east wall of second floor Center Hall (Room 201), looking down service passage
- MD-1149-30 View of Southwest Bedroom (Room 203), looking east, with scale stick
- MD-1149-31 View of service wing Bedroom (Room 209), looking east, with scale stick
- MD-1149-32 View of service wing attic, looking east
- MD-1149-33 Detail of dormer in service wing attic
- MD-1149-34 View of furnace in northeast cellar room